



# Build 1

Rev A	2008-06-04	
Rev B	2008-06-04	Fixed error in lower right view
Rev C		



## Hardware:

- 2X M4 x 8 mm (McMaster 91292A108)
- 2X M4 x 10 mm (McMaster 91292A116)
- 4X Belleville washers 0.281 x 0.138 x 0.010 (McMaster 9712K11)



<b>LDSS focus encoder</b>		
Units: millimeters		
Material: Aluminum		
Black anodize		
Change to 8600 Mag Ops		
<b>P103 LVDT bracket</b>		<b>Rev B</b>
Uomoto		
626-304-0278		